

NYISO Operator Initiated Commitment

Insert Time	Event Start Time	Event End Time	PTID	Resource Name	Requestor	Commitment Type	Load Zone of Resource	Commitment Reason	ARR	UOL	MW Committed
10-Jun-2020 08:24:26	10-Jun-2020 08:00:00	10-Jun-2020 23:00:00	23814	GLOBAL GREEN_PORT_GT1	TO	Received OOM	LONGIL	Constraint Management	-	49	49
10-Jun-2020 10:44:07	10-Jun-2020 10:00:00	10-Jun-2020 11:00:00	23712	GLENWOOD_IC_1_G5	NYISO	Received OOM	LONGIL	Constraint Management	-	15.3	0
10-Jun-2020 10:47:13	10-Jun-2020 10:00:00	10-Jun-2020 11:00:00	23712	GLENWOOD_IC_1_G5	NYISO	Deleted OOM	LONGIL	Constraint Management	-	15.3	0
10-Jun-2020 10:50:52	10-Jun-2020 10:00:00	10-Jun-2020 11:00:00	24220	KEDC_GLWD_GT5	NYISO	Received OOM	LONGIL	Constraint Management	-	47	0
10-Jun-2020 11:02:56	10-Jun-2020 11:00:00	10-Jun-2020 11:00:00	24220	KEDC_GLWD_GT5	NYISO	Modified OOM	LONGIL	Constraint Management	-	44	44
10-Jun-2020 11:08:05	10-Jun-2020 11:00:00	10-Jun-2020 23:00:00	323757	CRICKET___VALLEY_CC2	NYISO	Received OOM	HUD VL	Constraint Management	-	188	0
10-Jun-2020 11:08:33	10-Jun-2020 11:00:00	10-Jun-2020 23:00:00	323758	CRICKET___VALLEY_CC3	NYISO	Received OOM	HUD VL	Constraint Management	-	188	0
10-Jun-2020 11:09:01	10-Jun-2020 11:00:00	10-Jun-2020 23:00:00	323721	CPV_VALLEY___CC1	NYISO	Modified OOM	HUD VL	Constraint Management	-	188	0
10-Jun-2020 11:11:39	10-Jun-2020 11:00:00	10-Jun-2020 23:00:00	323721	CPV_VALLEY___CC1	NYISO	Deleted OOM	HUD VL	Constraint Management	-	188	0
10-Jun-2020 11:12:14	10-Jun-2020 11:00:00	10-Jun-2020 23:00:00	323756	CRICKET___VALLEY_CC1	NYISO	Modified OOM	HUD VL	Constraint Management	-	188	0
10-Jun-2020 11:15:37	10-Jun-2020 11:00:00	10-Jun-2020 23:00:00	23814	GLOBAL GREEN_PORT_GT1	TO	Deleted OOM	LONGIL	Constraint Management	-	49	49
10-Jun-2020 12:13:34	10-Jun-2020 12:00:00	10-Jun-2020 23:00:00	24216	PPL PILGRIM_ST_GT1	TO	Received OOM	LONGIL	Constraint Management	-	43	43
10-Jun-2020 12:22:32	10-Jun-2020 12:00:00	10-Jun-2020 23:00:00	323756	CRICKET___VALLEY_CC1	NYISO	Deleted OOM	HUD VL	Constraint Management	-	188	0
10-Jun-2020 12:22:32	10-Jun-2020 12:00:00	10-Jun-2020 23:00:00	323757	CRICKET___VALLEY_CC2	NYISO	Deleted OOM	HUD VL	Constraint Management	-	188	0
10-Jun-2020 12:22:32	10-Jun-2020 12:00:00	10-Jun-2020 23:00:00	323758	CRICKET___VALLEY_CC3	NYISO	Deleted OOM	HUD VL	Constraint Management	-	188	0
10-Jun-2020 13:14:58	10-Jun-2020 13:00:00	10-Jun-2020 23:00:00	323756	CRICKET___VALLEY_CC1	NYISO	Modified OOM	HUD VL	Constraint Management	-	225	0
10-Jun-2020 13:15:25	10-Jun-2020 13:00:00	10-Jun-2020 23:00:00	323757	CRICKET___VALLEY_CC2	NYISO	Received OOM	HUD VL	Constraint Management	-	225	0
10-Jun-2020 13:15:54	10-Jun-2020 13:00:00	10-Jun-2020 23:00:00	323758	CRICKET___VALLEY_CC3	NYISO	Received OOM	HUD VL	Constraint Management	-	325	0
10-Jun-2020 13:16:07	10-Jun-2020 13:00:00	10-Jun-2020 23:00:00	323758	CRICKET___VALLEY_CC3	NYISO	Modified OOM	HUD VL	Constraint Management	-	225	0
10-Jun-2020 13:56:03	10-Jun-2020 13:00:00	10-Jun-2020 23:00:00	24217	PPL PILGRIM_ST_GT2	TO	Received OOM	LONGIL	Constraint Management	-	46	46
10-Jun-2020 13:57:12	10-Jun-2020 13:00:00	10-Jun-2020 23:00:00	24217	PPL PILGRIM_ST_GT2	TO	Modified OOM	LONGIL	Constraint Management	-	44	44
10-Jun-2020 15:38:02	10-Jun-2020 15:00:00	10-Jun-2020 23:00:00	24217	PPL PILGRIM_ST_GT2	TO	Deleted OOM	LONGIL	Constraint Management	-	44	44
10-Jun-2020 16:46:38	10-Jun-2020 16:00:00	10-Jun-2020 23:00:00	23722	EAST_HAMPTON___DIESEL	TO	Received OOM	LONGIL	Constraint Management	-	6	6
10-Jun-2020 17:40:17	10-Jun-2020 17:00:00	10-Jun-2020 23:00:00	23695	HOLTSVILLE_IC_6	TO	Received OOM	LONGIL	Constraint Management	-	47	47
10-Jun-2020 19:08:17	10-Jun-2020 19:00:00	10-Jun-2020 23:00:00	23698	HOLTSVILLE_IC_9	TO	Received OOM	LONGIL	Constraint Management	-	65.5	46
10-Jun-2020 19:28:35	10-Jun-2020 19:00:00	10-Jun-2020 23:00:00	23696	HOLTSVILLE_IC_7	TO	Received OOM	LONGIL	Constraint Management	-	64.1	46
10-Jun-2020 19:34:32	10-Jun-2020 19:00:00	10-Jun-2020 23:00:00	323756	CRICKET___VALLEY_CC1	NYISO	Modified OOM	HUD VL	Constraint Management	-	300	0
10-Jun-2020 19:34:46	10-Jun-2020 19:00:00	10-Jun-2020 23:00:00	323757	CRICKET___VALLEY_CC2	NYISO	Modified OOM	HUD VL	Constraint Management	-	300	0
10-Jun-2020 19:34:58	10-Jun-2020 19:00:00	10-Jun-2020 23:00:00	323758	CRICKET___VALLEY_CC3	NYISO	Modified OOM	HUD VL	Constraint Management	-	300	0
10-Jun-2020 20:05:10	10-Jun-2020 20:00:00	10-Jun-2020 23:00:00	23722	EAST_HAMPTON___DIESEL	TO	Deleted OOM	LONGIL	Constraint Management	-	6	6
10-Jun-2020 20:05:10	10-Jun-2020 20:00:00	10-Jun-2020 23:00:00	23695	HOLTSVILLE_IC_6	TO	Deleted OOM	LONGIL	Constraint Management	-	47	47
10-Jun-2020 20:59:07	10-Jun-2020 20:00:00	10-Jun-2020 23:00:00	23696	HOLTSVILLE_IC_7	TO	Deleted OOM	LONGIL	Constraint Management	-	64.1	46
10-Jun-2020 20:59:08	10-Jun-2020 20:00:00	10-Jun-2020 23:00:00	23698	HOLTSVILLE_IC_9	TO	Deleted OOM	LONGIL	Constraint Management	-	65.5	46
10-Jun-2020 20:59:08	10-Jun-2020 20:00:00	10-Jun-2020 23:00:00	24216	PPL PILGRIM_ST_GT1	TO	Deleted OOM	LONGIL	Constraint Management	-	43	43

10-Jun-2020 21:06:06	10-Jun-2020 21:00:00	10-Jun-2020 23:00:00	323756	CRICKET___VALLEY_CC1	NYISO	Modified OOM	HUD VL	Constraint Management	-	275	0
10-Jun-2020 21:06:15	10-Jun-2020 21:00:00	10-Jun-2020 23:00:00	323757	CRICKET___VALLEY_CC2	NYISO	Modified OOM	HUD VL	Constraint Management	-	275	0
10-Jun-2020 21:06:36	10-Jun-2020 21:00:00	10-Jun-2020 23:00:00	323758	CRICKET___VALLEY_CC3	NYISO	Modified OOM	HUD VL	Constraint Management	-	275	0
10-Jun-2020 21:35:28	11-Jun-2020 00:00:00	11-Jun-2020 23:00:00	323756	CRICKET___VALLEY_CC1	NYISO	Received OOM	HUD VL	Constraint Management	-	275	0
10-Jun-2020 21:35:28	11-Jun-2020 00:00:00	11-Jun-2020 23:00:00	323757	CRICKET___VALLEY_CC2	NYISO	Received OOM	HUD VL	Constraint Management	-	275	0
10-Jun-2020 21:35:28	11-Jun-2020 00:00:00	11-Jun-2020 23:00:00	323758	CRICKET___VALLEY_CC3	NYISO	Received OOM	HUD VL	Constraint Management	-	275	0
10-Jun-2020 21:59:13	10-Jun-2020 21:00:00	11-Jun-2020 23:00:00	323756	CRICKET___VALLEY_CC1	NYISO	Modified OOM	HUD VL	Constraint Management	-	250	0
10-Jun-2020 21:59:24	10-Jun-2020 21:00:00	11-Jun-2020 23:00:00	323757	CRICKET___VALLEY_CC2	NYISO	Modified OOM	HUD VL	Constraint Management	-	250	0
10-Jun-2020 21:59:36	10-Jun-2020 21:00:00	11-Jun-2020 23:00:00	323758	CRICKET___VALLEY_CC3	NYISO	Modified OOM	HUD VL	Constraint Management	-	250	0